




4622




WICHTIG - FÜR SPÄTERE VERWENDUNG
AUFBEWAHREN - SORGFÄLTIG LESEN

AVIS - Ces instructions doivent être sauvegardées
Pour utilisation future - Les instructions doivent
être suivies

IMPORTANTE, conservar estas instrucciones
para futuro uso. Siga estas instrucciones atentamente

VIGTIGT - Samvejledningen skal opbevares
i arkiv til senere brug - Skal gennemlæses nøje

NOTICE - These instructions must be saved
for future use - Instructions must be followed



TEILCHECKLISTE
 LISTE DE CONTROLE
 LISTADO DE CONTROL
 TJEKLISTE
 CHECK LIST

46223052

Réf./No.	Réf./Art.	Qty./Stck./Quantité	Size / Maß / Dimension (mm)	Packed in box	✓
1	328691305	1	Φ500x18	1	
2	328692305	1	Φ323x18	1	
3	328693305	2	514x198x16	1	
4	328694305	1	514x198x16	1	
5	328695305	1	Φ299x524	1	

46224642

Réf./No.	Réf./Art.	Qty./Stck./Quantité	Size / Maß / Dimension (mm)	Packed in box	✓
1	328691464	1	Φ500x18	1	
2	328692464	1	Φ323x18	1	
3	328693464	2	514x198x16	1	
4	328694464	1	514x198x16	1	
5	328695464	1	Φ299x524	1	

46222782






Réf./No.	Réf./Art.	Qty./Stck./Quantité	Size / Maß / Dimension (mm)	Packed in box	✓
1	328691278	1	F 500x18	1	
2	328692278	1	F 323x18	1	
3	328693278	2	514x198x16	1	
4	328694278	1	514x198x16	1	
5	328695278	1	F 299x524	1	

46222932

Réf./No.	Réf./Art.	Qty./Stck./Quantité	Size / Maß / Dimension (mm)	Packed in box	✓
1	328691293	1	F 500x18	1	
2	328692293	1	F 323x18	1	
3	328693293	2	514x198x16	1	
4	328694293	1	514x198x16	1	
5	328695293	1	F 299x524	1	

TEILCHECKLISTE - LISTE DE CONTROLE - LISTADO DE CONTROL- TJEKLISTE - CHECK LIST

Réf./No.	Réf./Art.	Qty./Stck./Quantité	✓
A	228690	12	
B	228690	5	
C	228690	5	
E	228690	11	
F	228690	1	

12 - A	5 - B	5 - C	11 - E	1 - F	
 Ø8x30mm	 Ø10x43.5mm	 Ø15x11mm	 Ø7x50mm	 4mm	


Geehrter Kunde.
Hier haben Sie die Möglichkeit die mitgelieferten
Schrauben nachzumessen.

Cher Client.
La règle ci jointe vous permet de mesurer la visserie.

Estimado cliente.
aquí podrá medir la tornillería adjunta.

Kære kunde.
Her har De muligheden for at måle medsendte beslag.


Dear Customer.
Below you have the opportunity to measure the
Enclosed Hardware.



1 12 - A



Diagram showing a cylindrical pin labeled '1' and a reference number '12 - A'. A hammer icon is shown to the right.




2 6 - E






1 - F



Diagram showing a screw labeled '2' and a reference number '6 - E'. A screwdriver icon is shown to the right with the reference number '1 - F'.




3 5 - B



4 5 - C



5



6 5 - E 1 - F

